

$\begin{array}{c} 0.D. = .250\\ 1.D. = .100\\ \end{array}$ $\begin{array}{c} 0.D. = .250\\ 1.D. = .110\\ \end{array}$ $\begin{array}{c} 0.D. = .250\\ 1.D. = .125\\ \end{array}$ $\begin{array}{c} 0.D. = .250\\ 1.D. = .125\\ \end{array}$ $\begin{array}{c} 0.D. = .250\\ 1.D. = .150\\ \end{array}$ $\begin{array}{c} 0.D. = .250\\ 1.D. = .150\\ \end{array}$ $\begin{array}{c} 0.D. = .250\\ 1.D. = .170\\ \end{array}$ $\begin{array}{c} 0.D. = .250\\ 1.D. = .170\\ \end{array}$ $\begin{array}{c} 0.D. = .250\\ 1.D. = .150\\ \end{array}$ $\begin{array}{c} 0.D. = .156\\ 1.D. = .080\\ \end{array}$ $\begin{array}{c} 0.D. = .156\\ 1.D. = .088\\ \end{array}$ $\begin{array}{c} 0.D. = .156\\ 1.D. = .001\\ \end{array}$	
I.D. = .110         O.D. = .250         I.D. = .125         O.D. = .250         I.D. = .150         O.D. = .250         I.D. = .170         O.D. = .250         I.D. = .170         O.D. = .250         I.D. = .150         O.D. = .250         I.D. = .170         O.D. = .250         I.D. = .157         O.D. = .156         I.D. = .080         O.D. = .156         I.D. = .088         O.D. = .156         I.D. = .100         O.D. = .156	
I.D. = .125         O.D. = .250         I.D. = .150         O.D. = .250         I.D. = .170         O.D. = .250         I.D. = .170         O.D. = .250         I.D. = .157         O.D. = .156         I.D. = .080         O.D. = .156         I.D. = .088         O.D. = .156         I.D. = .100         O.D. = .156	
I.D. = .150         O.D. = .250         I.D. = .170         O.D. = .250         I.D. = .170         O.D. = .250         I.D. = .157         O.D. = .156         I.D. = .080         O.D. = .156         I.D. = .088         O.D. = .156         I.D. = .100         O.D. = .156	
I.D. = .170         O.D. = .250         I.D. = .157         O.D. = .156         I.D. = .060         O.D. = .156         I.D. = .080         O.D. = .156         I.D. = .088         O.D. = .156         I.D. = .100         O.D. = .156	
I.D. = .157         O.D. = .156         I.D. = .060         O.D. = .156         I.D. = .080         O.D. = .156         I.D. = .088         O.D. = .156         I.D. = .100         O.D. = .156	
I.D. = .060 I.D. = .156 I.D. = .080 O.D. = .156 I.D. = .088 O.D. = .156 I.D. = .088 O.D. = .156 I.D. = .100 O.D. = .156	
I.D. = .080         O.D. = .156         I.D. = .088         O.D. = .156         I.D. = .100         O.D. = .156	
I.D. = .088 O.D. = .156 I.D. = .100 O.D. = .156	
I.D. = .100 O.D. = .156	
	O.D. = .156